

Wood River Sulfuric Acid Release

Photo Log

Description: Water curtain provided by local fire department

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: Later on Thursday the second day of incident

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: Same

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: Same

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: A view from the west side of the RR ROW

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Wood River Sulfuric Acid Release

Photo Log

Description: West side of rail cars

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: Command Post located on Rand Avenue

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: OSC Vrabec in discussion with IEPA OER staff

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: Norfolk and Southerns contractors preparing AreaRAE instruments for deployment


Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: 1100 hours Ops briefing

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Wood River Sulfuric Acid Release

Photo Log

Description: Rand Avenue intersection of RR ROW crossing

Category: Site Photo

Latitude:

Date Taken: 6/3/2021

Longitude:

Tags:



Description: START Mobile Field Office with host controller, gateway and equipment charging at Station #1.

Category: Site Photo

Latitude:

Date Taken: 6/5/2021

Longitude:

Tags:



Description: START Air Monitoring Station #1

Category: Site Photo

Latitude:

Date Taken: 6/5/2021

Longitude:

Tags:



Description: START Air Monitoring Station #2 with AreaRAE and SPM Flex data stream via VIPER

Category: Site Photo

Latitude:

Date Taken: 6/5/2021

Longitude:

Tags:



Description: START Air Monitoring Station #3 - Wood River Police Station

Category: Site Photo

Latitude:

Date Taken: 6/5/2021

Longitude:

Tags:



Wood River Sulfuric Acid Release

Photo Log

Description: START Air Monitoring Station #4

Category: Site Photo

Latitude:

Date Taken: 6/5/2021

Longitude:

Tags:



Description: Air Monitoring Station #5 - AreaRAE only.

Category: Site Photo

Latitude:

Date Taken:

Longitude:

Tags:



Description: Drone image on Sunday, June 6, 2021

Category: Site Photo

Latitude: 38.8322842027143

Date Taken: 6/6/2021

Longitude: -90.0808868143968

Tags:



Description: Drone image from Sunday, June 6, 2021

Category: Site Photo

Latitude: 38.8322327800952

Date Taken: 6/6/2021

Longitude: -90.0810028070238

Tags:



Description: Drone image of the Site.

Category: Site Photo

Latitude: 38.832267224746

Date Taken: 6/6/2021

Longitude: -90.0809631750794

Tags:



Wood River Sulfuric Acid Release

Photo Log

Description: Scrubbers used for vapors

Category: Site Photo

Latitude: 38.8324989498333

Date Taken: 6/6/2021

Longitude: -90.0804228324564

Tags:



Description: Overflight of stressed vegetation

Category: Site Photo

Latitude: 38.8312054934365

Date Taken: 6/6/2021

Longitude: -90.0800312621944

Tags:



Description: Shroud placed over dome and vacuum conveyance lines used to control vapors


Category: Site Photo

Latitude: 38.8320673313492

Date Taken: 6/6/2021

Longitude: -90.0804280527897

Tags:



Description: START air quality monitoring near the ARC building

Category: Site Photo

Latitude:

Date Taken: 6/8/2021

Longitude:

Tags:



Description: MultiRAE Pro collecting data near the ARC buildings.


Category: Site Photo

Latitude:

Date Taken: 6/8/2021

Longitude:

Tags:



Wood River Sulfuric Acid Release

Photo Log

Description: Railcars shown in the distance to the left.

Category: Site Photo

Latitude:

Date Taken: 6/8/2021

Longitude:

Tags:



Description: Four rail cars (white) moving along siding to the east

Category: Site Photo

Latitude:

Date Taken: 6/8/2021

Longitude:

Tags:



Description: Moving railcars easterly back into the nearby Conoco Phillips refinery.

Category: Site Photo

Latitude:

Date Taken: 6/8/2021

Longitude:

Tags:



Description: Last railcars moving towards the refinery.

Category: Site Photo

Latitude:

Date Taken: 6/8/2021

Longitude:

Tags:



Description: Same

Category: Site Photo

Latitude:

Date Taken: 6/8/2021

Longitude:

Tags:



Wood River Sulfuric Acid Release

Photo Log

Description: Railcars moving past the command post at 1840 hours.

Category: Site Photo Latitude:

Date Taken: 6/8/2021 Longitude:

Tags:



Description: Last photo of railcars moving towards the refinery.

Category: Site Photo Latitude:

Date Taken: 6/8/2021 Longitude:

Tags:

